Subject: Suite C 1718 N. Cherokee St. - HPOA Service Center

From: Sergio Urena <surena@streetplus.net>

Date: 01/09/2018 03:23 PM

To: Karina Beltran <kbeltran@charlesdunn.com>

CC: Matthew Severson < Matthew@hollywoodbid.org>, Rich Sarian < Rich@hollywoodbid.org>, Ken Nakano < knakano@streetplus.net>

Greetings Ms. Beltran,

Thank you for responding to our need so quickly. I took the pictures of where the water has gone to inside the service center. These unfortunately are after we have cleaned-up the water. However, they do show the areas that we are talking about. I believe that once the water passing thru the front door, it then seeps thru and underneath the dry wall and into the other rooms.


The picture that shows a black metal grate (pic 145835) is what should be draining the majority of the water. We have tried opening it to clean out the debris but I believe they are integrated into the concrete. The side walk is also an issue, due to a tree root lifted the front slab and directing the water back towards the door.

We are currently trying some sand bags to see it they help for today's remaining rains.

Thank you again.

Sergio M. Ureña | Program Manager *Hollywood Entertainment / Sunset & Vine Districts* **Service Hotline:** 323-204-6439


-20180109 145938 resized.jpg-




-20180109_145835_resized.jpg-




-20180109_145751_resized.jpg-




-20180109_145505_resized.jpg-



-20180109_145456_resized.jpg-



-20180109_145441_resized.jpg-



- Attachments:	
-Attachments.	
20180109 145938 resized.jpg	105 KB
20100109_1+3930_1c3i2cd.jpg	103 KB
20180109 145835 resized.jpg	128 KB
20100103_143033_1C3i2Cd.jpg	120 KB
20180109 145751 resized.jpg	131 KB
20100103_143731_1C3i2Cd.jpg	
20180109 145505 resized.jpg	113 KB
20100103_1+3303_1e3i2ed:jpg	
20180109 145456 resized.jpg	85.9 KB
20100103_1+3+30_1e3i2edijpg	
20180109 145441 resized.jpg	115 KB
20100103_14341_1631264.jpg	113 10